# Lauck Testing Laboratories, Inc.



LABORATORY NO. 10158

DATE: June 10, 1988

PO# M6104

940 South Harney St., Seattle, Washington 98108 (206) 767-5060 FAX 767-5063

Chemistry, Microbiology, and Technical Services

CLIENT: Alaskan Copper Works

P.O. Box 3546

Seattle, WA 98124

ATTN: Jim Brown

REPORT ON: WASTE DISCHARGE

**SAMPLE** 

IDENTIFICATION: Submitted 06/01/88 and identified as shown below:

ID# 5-3-3200-M6104

2) ID# 5-5-3200-M6104

3) ID# 5-10-3200-M6104

4) ID# 5-17-3200-M6104

5) ID# 5-12-3200-M6104

ID# 5-19-3200-M6104 6)

ID# 5-24-3200-M6104

ID# 5-26-3200-M6104

TESTS PERFORMED AND RESULTS:

### parts per million (mg/L)

	1	2	3	4	5
Zinc	0.062	0.092	0.080	0.086	0.13
Chromium	0.40	0.64	0.64	0.67	0.78
Copper	0.34	0.47	0.25	0.56	0.50
Nickel	0.46	0.49	0.40	0.52	0.52
	6	7	8	Method <u>Blank</u>	
Zinc	0.35	0.11	0.089	<0.002	
Chromium	5.7	0.48	0.47	<0.005	
Copper	1.3	0.35	0.46	<0.002	
Nickel	2.6	0.37	0.32	<0.01	



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.





940 South Harney St., Seattle, Washington 98108 (206) 767-5060 FAX 767-5063

Chemistry Microbiology, and Technical Services

Alaskan Copper Works

PAGE NO. 2 LABORATORY NO. 10158

<u>Key</u>

< indicates "less than"

Respectfully submitted,

Laucks Testing Laboratories, Inc.

Barbara GTeason

BG:emt



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.





940 South Harney St., Seattle, Washington 98108 (206) 767-5060 FAX 767-5063

Chemistry Microbiology, and Technical Services

#### **APPENDIX**

## Matrix Spike/Matrix Spike Duplicate Report

## Inorganics/Metals Analyses

		parts per million (mg/L)			mg/L					
		Spike	Sample	MS	%	MSD	%		QC Limits	
<u>Sample</u>	<u>Analyte</u>	Added	Result	Result	Rec	Result	<u>Rec</u>	<u>RPD</u>	RPD	REC
1	Chromium	0.100	0.40	0.46	60.	0.48	80.	29.	Comment A	
1	Zinc	0.100	0.062	0.15	83.	0.15	88.	6.	6	64-127
1	Copper	0.100	0.34	0.38	42.	0.39	45.	6.	Comment A	
1	Nickel	0.200	0.46	0.59	68.	0.60	72.	6.	5	66-125

MS = Matrix Spike

MSD = Matrix Spike Duplicate

Rec = Recovery

RPD = Relative Percent Difference

Comment A. Samples are spiked prior to preparation and analysis at a level deemed to be generally appropriate to the average sample processed in the laboratory. In this case, the level of analyte already present in the sample was large enough to make an accurate determination of spike recovery impossible.



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.